




Pinkwood PKjoists® Web Repair with Services Remaining

I-joist web repair for holes

When holes are cut in the wrong location through the web of a PKjoist®, it is recommended to remove the service item and patch the hole per **TB12 "Standard Web Repair"**. When this is not practical and the penetrating item must remain as placed, the following detail can be used to restore the joist allowable shear with the following hole size and location restrictions.



Restrictions

Joist Series	Joist Depth	Penetration within First 1/3 Span			Penetration within Middle 1/3 Span		
		Round	Rectangular		Round	Rectangular	
		Max (D)	Max (L)	Max (H)	Max (D)	Max (L)	Max (H)
PKI 10, 20, 23, 35Plus, 40, 50	9-1/2"	4-1/2"	14"	5"	6-1/2"	16"	6"
	11-7/8"	5"	16"	7"	8-7/8"	18"	8-3/8"
	14"	5-1/2"	18"	8-1/2"	11"	18"	10-1/2"
	16"	6-1/2"	18"	10"	13"	18"	12-1/2"
PKI 60L, 70L	9-1/2"	4-1/2"	14"	5"	6-1/2"	16"	6"
	11-7/8"	5"	16"	7"	8-7/8"	18"	8-3/8"
	14"	5-1/2"	18"	8-1/2"	11"	18"	10-1/2"
	16"	6-1/2"	18"	10"	13"	18"	12-1/2"
PKI 80L, 90L	9-1/2"	4-1/2"	14"	5"	6-1/2"	16"	6"
	11-7/8"	5"	16"	7"	8-7/8"	18"	8-3/8"
	14"	5-1/2"	18"	8-1/2"	11"	18"	10-1/2"
	16"	6-1/2"	18"	10"	13"	18"	12-1/2"

Installation Notes

1. Fill web with rated sheathing flush to outside of flanges, both sides, cut tightly around hole.
2. Apply construction adhesive to all contact surfaces of panel pieces.
3. Apply second layer of 23/32" rated panel, one side, cut tightly around hole.
4. Apply construction adhesive to entire backside and top edge of panel.
5. Secure to flanges and base layer with 8d nails x 2.5" long, 6 rows at 4" o.c.

If you have any questions, please contact XP-EWP for details.

Pinkwood® and PKjoist® are registered trademarks and not the property of XP-EWP. Contact their respective owners for information.

XP-EWP

14523 S. Palo Alto Drive,
Herriman UT 84096

Contact johnd@xp-ewp for more details

TECHNICAL BULLETIN
TB15

January 2026